
STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291

Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	Genera	<u>l Information</u>		
	1.	Report Time Period: From (mo./yr.) 1/2001 To (mo./yr.) 12/2001		
	2.	DOGM File Number (Mine No): S / 035/17		
	3.	Mine Name: Little Cottonwood-Granite Extraction		
	4.	Mineral(s) Mined (or permitted to mine): Granite		
	5.	Type of mine		
	6.	Legal Description (Location of Lands Affected):		
		<u>NW</u> 1/4, <u>SW</u> 1/4, <u>1/4, Section 8</u> , Township <u>T35</u> , Range <u>R-2E</u> 1/4,1/4, Section, Township, Range		
7	Nama			
7.	Name of Operator or Company: Corp. of Presiding Bishop			
	8.	Permanent Street Address: 15 East South Temple Street		
		City, State, Zip: Salt Lake City, Utah 84150-6330		
		Phone: (801) 240-6448 Fax: (801) 240-1335		
	9.	Company Representative (or designated operator):		
		Name: Kerry B. Nielsen, AIA		
		Title: Project Architect/Project Manager		
		Business Address: 15 East South Temple Street		
		City, State, Zip: Salt Lake City, Utah 84150-6330		
		Phone: (801) 240-6448 Fax: (801) 240-1335		
		Please check if any of the above information has changed since previous year.		
II.	Mining	Mining and Reclamation		
	1.	Was there any mine related activity during the past year? Yes □ No ☒		
	2.	If no - what was the last year of activity? 1999		
	3.	If yes - how much ore or mineral was mined? NA		

4.	Briefly describe the type of work performed, volume of marial moved, and any new or additional surface disturbances that occurred during the past year.			
	Mineral extraction ended			
		regrading rock, stabilization and row		
	revegitation, trees, shru	ubs, and seed.		
5.	How much additional acreage was disturbed during the past year?0			
6.	How much acreage was reclaimed during the past year? 4.5 Acres			
7.	should include methods employed, an See #4	performed during the past year. This description d an evaluation of the results.		
	Second planting of 300 trees and shrubs was completed			
	October 2001. Restoration work very successful.			
8.	What is the total disturbed acreage of entire project at years end?			
9.	Briefly summarize any mining and/or reclamation plans for the upcoming year. None-			
	Reclamation complete			
	Signs and perimeter fence will be removed.			
		(App. 40)		
NOTE:	Section III., "Additional Information"	applies only to large mining operations.		
III. Additiona	al Information - R647-4-121.2 and .3			
1.	The operator shall include an updated performed during the year, prepared i	I map depicting surface disturbance and reclamation n accordance with Rule R647-4-105.		
2.	The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.			
IV. <u>Signatur</u>	re Requirement			
I he	reby certify that the foregoing is tr	ue and correct.		
	Name (Typed or Print):	Kerry B. Nielsen, AIA		
	Title of Operator:	Project Architect for Owner		
	Signature of Operator:			
	Date:	12.21.200		
jb		l v		
o:\forms\reports\MR	-AR	DECEIVER		

DIV. OF OIL, GAS & MINING